

**Table 1 - Summary of Results**

Date	Atlantic Sample #	Layer	Diagram location number	Building area	Location (refer to diagrams)	Suspect material	Friability	Condition of Friable		Estimated Quantity of Homogeneous	
								ACM	H.A.	ACM	% asbestos
9/17/16	I1716-101	n/a	1	2FL	Bath	12x12 P&S floor tile	Non-friable	n/a	A	n/a	NAD
9/17/16	I1716-102	n/a	2	2FL	Bath	12x12 P&S floor tile	Non-friable	n/a	A	n/a	NAD
9/17/16	I1716-103	n/a	3	2FL	Bath	Drywall	Friable	Good	B	See location 19	NAD
9/17/16	I1716-104	n/a	4	2FL	Bath	Joint compound	Friable	Good	B		NAD
9/17/16	I1716-105	n/a	5	2FL	Kitchen	Drywall	Friable	Good	B		NAD
9/17/16	I1716-106	n/a	6	2FL	Kitchen	Joint compound	Friable	Good	B		NAD
9/17/16	I1716-107	n/a	7	1FL	Kitchen	12x12 P&S floor tile	Non-friable	n/a	C	n/a	NAD
9/17/16	I1716-108	n/a	8	1FL	Kitchen	12x12 P&S floor tile	Non-friable	n/a	C	n/a	NAD
9/17/16	I1716-109	n/a	9	1FL	Foyer	Gray vinyl flooring	Non-friable	n/a	D	n/a	NAD
9/17/16	I1716-110	n/a	10	1FL	Foyer	Gray vinyl flooring	Non-friable	n/a	D	n/a	NAD
9/17/16	I1716-111	n/a	11	1FL	Bath	Floor coating	Non-friable	n/a	E	n/a	NAD
9/17/16	I1716-112	n/a	12	1FL	Bath	Floor coating	Non-friable	n/a	E	n/a	NAD
9/17/16	I1716-113	n/a	13	1FL	Bath	2x4 ceiling tile	Friable	n/a	F	n/a	NAD
9/17/16	I1716-114	n/a	14	1FL	Bath	2x4 ceiling tile	Friable	n/a	F	n/a	NAD
9/17/16	I1716-115	n/a	15	1FL	LR	1x1 ceiling tile	Friable	n/a	G	n/a	NAD
9/17/16	I1716-116	n/a	16	1FL	LR	1x1 ceiling tile	Friable	n/a	G	n/a	NAD
9/17/16	I1716-117	n/a	17	1FL	BR	Drywall	Friable	Good	H	1,500 s.f.	Presumed
9/17/16	I1716-118	n/a	18	1FL	BR	Drywall	Friable	Good	H		Presumed
9/17/16	I1716-119	n/a	19	1FL	BR	Joint compound	Friable	Good	H		1.9%
9/17/16	I1716-120	n/a	20	1FL	BR	Joint compound	Friable	Good	H		PS
9/17/16	I1716-121	n/a	21	Basement	Walls	Cementitious parging	Friable	n/a	I	n/a	NAD
9/17/16	I1716-122	n/a	22	Basement	Walls	Cementitious parging	Friable	n/a	I	n/a	NAD
9/17/16	I1716-123	n/a	23	Basement	Chimney	Flue cement	Friable	n/a	J	n/a	NAD
9/17/16	I1716-124	n/a	24	Basement	Chimney	Flue cement	Friable	n/a	J	n/a	NAD
9/17/16	I1716-125	n/a	25	Exterior	2FL R window	Glazing compound	Non-friable	n/a	K	n/a	NAD
9/17/16	I1716-126	n/a	26	Exterior	1FL front window	Glazing compound	Non-friable	n/a	K	n/a	NAD
9/17/16	I1716-127	n/a	27	Exterior	Walls	Cementitious (Transite) siding	Non-friable	n/a	L	2,200 s.f.	26.7%
9/17/16	I1716-128	n/a	28	Exterior	Walls	Cementitious (Transite) siding	Non-friable	n/a	L		PS

Table 1 Notes:

Orange highlighting indicates samples with greater than 1% asbestos - POSITIVE or presumed

NAD = No asbestos

PS = Positive Stop: the sample or layered system is presumed to contain asbestos

H.A. = Homogeneous Area