

Table 1 - Summary of Results

Date	Atlantic Sample #	Layer	Diagram location number	Building area	Location (refer to diagrams)	Suspect material	Friability	Condition of Friable		Estimated Quantity of Homogeneous	
								ACM	H.A.	ACM	% asbestos
9/17/16	I1716-401	n/a	1	2FL	Kitchen	White vinyl flooring	Non-friable	n/a	A	n/a	NAD
9/17/16	I1716-402	n/a	2	2FL	Kitchen	White vinyl flooring	Non-friable	n/a	A	n/a	NAD
9/17/16	I1716-403	n/a	3	2FL	Bath	Thinset mortar	Friable	n/a	B	n/a	NAD
9/17/16	I1716-404	n/a	4	2FL	Bath	Thinset mortar	Friable	n/a	B	n/a	NAD
9/17/16	I1716-405	n/a	5	2FL	BR	Felt at wood floor	Non-friable	n/a	C	n/a	NAD
9/17/16	I1716-406	n/a	6	2FL	BR	Felt at wood floor	Non-friable	n/a	C	n/a	NAD
9/17/16	I1716-407	n/a	7	2FL	Foyer	2x4 ceiling tile	Friable	n/a	D	n/a	NAD
9/17/16	I1716-408	n/a	8	2FL	Foyer	2x4 ceiling tile	Friable	n/a	D	n/a	NAD
9/17/16	I1716-409	n/a	9	2FL	Kitchen	1x1 ceiling tile	Friable	n/a	E	n/a	NAD
9/17/16	I1716-410	n/a	10	2FL	Kitchen	1x1 ceiling tile	Friable	n/a	E	n/a	NAD
9/17/16	I1716-411	n/a	11	2FL	Stair closet	Plaster	Friable	n/a	F	n/a	NAD
9/17/16	I1716-412	n/a	12	2FL	Kitchen	Plaster	Friable	n/a	F	n/a	NAD
9/17/16	I1716-413	n/a	13	2FL	Kitchen	Plaster	Friable	n/a	F	n/a	NAD
9/17/16	I1716-414	n/a	14	1FL	Kitchen/bath	White vinyl flooring	Non-friable	n/a	G	n/a	NAD
9/17/16	I1716-415	n/a	15	1FL	Kitchen/bath	White vinyl flooring	Non-friable	n/a	G	n/a	NAD
9/17/16	I1716-416	n/a	16	1FL	Front stair	Red 12x12 floor tile	Non-friable	n/a	H	30 s.f.	1.4%
9/17/16	I1716-417	n/a	17	1FL	Front stair	Red 12x12 floor tile	Non-friable	n/a	H		PS
9/17/16	I1716-418	n/a	18	1FL	LR	1x1 ceiling tile (dot)	Non-friable	n/a	I	n/a	NAD
9/17/16	I1716-419	n/a	19	1FL	LR	1x1 ceiling tile (dot)	Non-friable	n/a	I	n/a	NAD
9/17/16	I1716-420	n/a	20	Basement	Chimney	Flue cement	Friable	Damaged	J	2 s.f.	3.5%
9/17/16	I1716-421	n/a	21	Basement	Chimney	Flue cement	Friable	Damaged	J		PS
9/17/16	I1716-422	n/a	22	Basement	Wall	Plaster	Friable	n/a	F	n/a	NAD
9/17/16	I1716-423	n/a	23	Basement	Ducts	Fabric duct wrap	Friable	Damaged	K	10 s.f.	36.4%
9/17/16	I1716-424	n/a	24	Basement	Ducts	Fabric duct wrap	Friable	Damaged	K		PS
9/17/16	I1716-425	n/a	25	Exterior	Window	Glazing compound	Non-friable	n/a	L	n/a	NAD
9/17/16	I1716-426	n/a	26	Exterior	L window	Glazing compound	Non-friable	n/a	L	n/a	NAD
9/17/16	I1716-427	n/a	27	Roof	R side	Bituminous ice-water membrane	Non-friable	n/a	M	n/a	NAD
9/17/16	I1716-428	n/a	28	Roof	R side	Bituminous ice-water membrane	Non-friable	n/a	M	n/a	NAD

Table 1 Notes:

Orange highlighting indicates samples with greater than 1% asbestos - POSITIVE or presumed

NAD = No asbestos

PS = Positive Stop: the sample or layered system is presumed to contain asbestos

H.A. = Homogeneous Area