

Table 2 - Homogeneous Areas

Area	Material	Locations	Friability	ACM? Y/N	Quantity of ACM
A	Green vinyl flooring	Second floor kitchen	Non-friable	Y	180 s.f.
B	White vinyl flooring	Second floor bath	Non-friable	N	N/A
C	Textured paint	Second floor front room	Friable	N	N/A
D	Plaster	Various walls and ceilings throughout structure	Friable	N	N/A
E	Green vinyl flooring	First floor kitchen	Non-friable	Y	330 s.f.
F	Wallpaper	First floor rear hall	Friable	N	N/A
G	1.5 x 1.5 ceiling tile	First floor living room	Friable	N	N/A
H	2 x 4 ceiling tile (new)	First floor living room	Friable	N	N/A
I	2 x 4 ceiling tile (old)	First floor living room	Friable	N	N/A
J	Drywall and join compound	Walls and ceilings throughout structure, mainly on first floor	Friable	Y	5,000 s.f.
K	Cementitious parging	Basement foundation wall	Non-friable	N	N/A
L	Flue cement	Basement chimney	Friable	N	N/A
M	Air cell pipe installation	Pipes in basement	Friable	Y	40 l.f.
N	Cementitious (Transite) siding	Exterior walls	Non-friable	Y	4,000 s.f.
O	Glazing compound	All old-style putty-glazed window sash	Non-friable	N	N/A
P	Cementitious parging	Exterior foundation walls	Non-friable	N	N/A
Q	Caulking	Exterior window perimeters	Non-friable	N	N/A
R	Fiberboard	Exterior siding underlayment	Friable	N	N/A

Table 2 Notes:

Orange highlighting indicates Asbestos Containing Materials

* Quantities are estimated and approximate: s.f. = square feet; l.f. = linear feet

218 WEST HENRY STREET, ELMIRA, NY
Pre-Demolition Asbestos Survey

p. 2 of 2

Table 2 - Homogeneous Areas

Area	Material	Locations	Friability	ACM? Y/N	Quantity of ACM
S	Asphaltic felt	Exterior rear walls	Non-friable	N	N/A
T	Asphaltic flashing cement	Rear wing walls	Non-friable	N	N/A
U	Asphaltic roofing	Rear wing roof (bottom layer)	Non-friable	N	N/A
V	Bituminous roll roofing	Front porch	Non-friable	N	N/A
W	Silver asphaltic coating	Right side metal roofs	Non-friable	Y	60 s.f.
X	Multilayer asphaltic shingles	Main roofing	Non-friable	N	N/A
Y	Asphaltic flashing cement	Roof joints and penetrations	Non-friable	N	N/A
Z	Cementitious (Transite) siding	Barn exterior walls	Non-friable	Y	2,500 s.f.
AA	Asphaltic felt underlayment	Barn exterior walls	Non-friable	N	N/A
BB	Glazing compound	All old-style putty-glazed window sash in barn	Non-friable	N	N/A
CC	Asphaltic felt and shingles	Barn porch roof	Non-friable	N	N/A
DD	Multilayer asphaltic shingles	Barn main roof	Non-friable	N	N/A

Table 2 Notes:

Orange highlighting indicates Asbestos Containing Materials

* Quantities are estimated and approximate: s.f. = square feet; l.f. = linear feet