

Table 1 - Summary of Results

| Date | Atlantic Sample # | Layer | Diagram location number | Building area | Location (refer to diagrams) | Suspect material | Friability | Condition of Friable | | Estimated Quantity of Homogeneous | |
|---------|-------------------|-------|-------------------------|---------------|------------------------------|---------------------------|-------------|----------------------|------|-----------------------------------|------------|
| | | | | | | | | ACM | H.A. | ACM | % asbestos |
| 9/17/16 | I1716-229 | n/a | 29 | 1FL | Rear bath | 12x12 floor tile | Non-friable | n/a | K | n/a | NAD |
| 9/17/16 | I1716-230 | n/a | 30 | 1FL | Rear bath | 12x12 floor tile | Non-friable | n/a | K | n/a | NAD |
| 9/17/16 | I1716-231 | n/a | 31 | 1FL | Kitchen | 12x12 floor tile | Non-friable | n/a | L | n/a | NAD |
| 9/17/16 | I1716-232 | n/a | 32 | 1FL | Kitchen | 12x12 floor tile | Non-friable | n/a | L | n/a | NAD |
| 9/17/16 | I1716-233 | n/a | 33 | 1FL | Bath wall | Mastic | Non-friable | n/a | M | n/a | NAD |
| 9/17/16 | I1716-234 | n/a | 34 | 1FL | Kitchen wall | Mastic | Non-friable | n/a | M | n/a | NAD |
| 9/17/16 | I1716-235 | n/a | 35 | 1FL | Mid | 2x4 ceiling tile | Friable | n/a | N | n/a | NAD |
| 9/17/16 | I1716-236 | n/a | 36 | 1FL | Mid | 2x4 ceiling tile | Friable | n/a | N | n/a | NAD |
| 9/17/16 | I1716-237 | n/a | 37 | 1FL | Side | Drywall | Friable | n/a | O | 3,000 s.f. | Presumed |
| 9/17/16 | I1716-238 | n/a | 38 | 1FL | L mid | Drywall | Friable | n/a | O | | Presumed |
| 9/17/16 | I1716-239 | n/a | 39 | 1FL | L BR | Joint compound | Friable | n/a | O | | 1.8% |
| 9/17/16 | I1716-240 | n/a | 40 | 1FL | Front | Joint compound | Friable | n/a | O | | PS |
| 9/17/16 | I1716-241 | n/a | 41 | Exterior | Wall | Felt | Non-friable | n/a | P | n/a | NAD |
| 9/17/16 | I1716-242 | n/a | 42 | Exterior | Wall | Felt | Non-friable | n/a | P | n/a | NAD |
| 9/17/16 | I1716-243 | n/a | 43 | Exterior | 2FL R | Glazing compound | Non-friable | n/a | Q | n/a | Trace |
| 9/17/16 | I1716-244 | n/a | 44 | Exterior | 1FL R | Glazing compound | Non-friable | n/a | Q | n/a | NAD |
| 9/17/16 | I1716-245 | n/a | 45 | Exterior | R side | Caulk | Non-friable | n/a | R | n/a | NAD |
| 9/17/16 | I1716-246 | n/a | 46 | Exterior | front | Caulk | Non-friable | n/a | R | n/a | NAD |
| 9/17/16 | I1716-247 | n/a | 47 | Roof | Porch | Bituminous roofing | Non-friable | n/a | S | 200 s.f. | PS |
| 9/17/16 | I1716-248 | n/a | 48 | Roof | Porch | Bituminous roofing | Non-friable | n/a | S | | 1.2% |
| 9/17/16 | I1716-249 | n/a | 49 | Roof | Main | Asphaltic felt | Non-friable | n/a | T | n/a | NAD |
| 9/17/16 | I1716-250 | n/a | 50 | Roof | Main | Asphaltic felt | Non-friable | n/a | T | n/a | NAD |
| 9/17/16 | I1716-251 | n/a | 51 | Roof | Main | Asphaltic shingle | Non-friable | n/a | T | n/a | NAD |
| 9/17/16 | I1716-252 | n/a | 52 | Roof | Main | Asphaltic shingle | Non-friable | n/a | T | n/a | NAD |
| 9/17/16 | I1716-253 | n/a | 53 | Roof | Main | Asphaltic flashing cement | Non-friable | n/a | U | n/a | Trace |
| 9/17/16 | I1716-254 | n/a | 54 | Roof | Main | Asphaltic flashing cement | Non-friable | n/a | U | n/a | Trace |

Table 1 Notes:

Orange highlighting indicates samples with greater than 1% asbestos - POSITIVE or presumed

NAD = No asbestos

PS = Positive Stop: the sample or layered system is presumed to contain asbestos

H.A. = Homogeneous Area